

MACHINE TOOL


GATE ESE-IES

* Parameter of Machining

(i:-) Cylindrical Turning :- Axial feed [feed is // to Axis of Revolution]

$$t_m = \frac{L_e}{fN} = \frac{L_a + L_w + L_o}{fN} = \text{min}$$

$$\frac{\text{mm}}{\text{rev}} \times \frac{\text{rev}}{\text{min}} = \frac{\text{mm}}{\text{min}} = \text{feed Velocity or Cutting Velocity}$$



* No approach and overtravel

$$t_m = \frac{L_e}{fN} = \frac{200}{1 \times 500} = 4 \text{ min}$$

* Cutting Velocity :-

$$V = \frac{\pi D N}{1000}$$

$$D = \text{mm}$$

$$V = \text{m/min}$$

$$N = \text{rpm}$$

$$N = \frac{V \times 1000}{\pi \times D}$$

* If V_{max} → given

$$N = \frac{V \times 1000}{\pi \times D_{max}}$$

If V_{min} → given


$$N = \frac{V \times 1000}{\pi \times D_{min}}$$

If V_{avg} → given

$$N = \frac{V \times 1000}{\pi \times D_{avg}}$$

* If Nothing mention, Velocity is max^m or min^m then take Average


* Depth of Cut (d) in Case of Turning and Boring



$$N_{turning} = \frac{V \times 1000}{\pi \times D_{max}}$$

$$D_{max} - 2d = D_{min}$$

$$d_T = \frac{D_{max} - D_{min}}{2}$$



$$N_{boring} = \frac{V \times 1000}{\pi \times D_{min}}$$

$$d_B = \frac{D_f - D_i}{2}$$

depth = 3 of cut

$$50 \xrightarrow{\text{depth=3 of cut}} 44 \Rightarrow \frac{50+44}{2}$$

$$D_{avg} = 47$$

Depth of Cut

(a) Turning

$$d_T = \frac{D_i - D_f}{2}$$

(b) For Boring


$$d_B = \frac{D_f - D_i}{2}$$

Note:- (1) $T_m = \frac{L_e \times n}{fN}$

{ where n = Number of Pass depends upon max^m depth of cut }

(2) If V = given then Calculate N step by step

(3)



v = tangential Velocity
or
Peripheral Velocity
Surface^o Velocity

F_c = tangential Force
(Cutting Force)

← This formula is applies when the direction of F_c and V are Same


$$\therefore \text{Power} = F_c \times v$$

2:- Facing

$$t_m = \frac{D/2}{F_x N}$$


F_x = feed is \perp to Axis of Revolution.

D = Diameter of Workpiece.



Mradul Rawat

Question:- Facing



$$D_{avg} = \frac{200 + 60}{2} = 140$$

$$F = 0.1 \text{ mm/rev}$$

$$V = 200 \text{ m/min}$$

$$t_m = ??$$


$$N = \frac{200 \times 1000}{\pi \times 140} = 454.72 \text{ rpm}$$

$$t_m = \frac{D/2}{F \times N} = \frac{120/2}{0.1 \times 454.72} = 1.319 \text{ min.}$$

Nothing given max/min then take Avg Velocity

(2)

* Taper Turning



L_t = length of taper
 L_w = length of workpiece

$$t_m = \frac{AC}{fN}$$


$$f = \sqrt{f_a^2 + f_r^2}$$

$$AC = \sqrt{L_t^2 + x^2}$$

$$(t_m)_{\text{taper}} = \frac{\sqrt{L_t^2 + x^2}}{\sqrt{f_a^2 + f_r^2} \cdot N}$$

Both axial and radial component of feed is provided.

(a) Calculation of taper Angle



$$D_{max} - D_{min} = 2x$$


$$D_{max} - 2x = D_{min}$$

$$x = \frac{D_{max} - D_{min}}{2}$$

$$\tan \frac{\alpha}{2} = \frac{x}{L_t} = \frac{D_{max} - D_{min}}{2L_t}$$

$$\alpha = 2 \tan^{-1} \left(\frac{D_{max} - D_{min}}{2L_t} \right)$$

(b) Tail stock offset Method or Setover method



$$\sin \frac{\alpha}{2} = \frac{x}{L_w}$$

$$x = L_w \sin \frac{\alpha}{2}$$

* IAS

Ques:- $D_{max} = 50 \text{ mm}$, $D_{min} = 38 \text{ mm}$, $L_w = 300 \text{ mm}$, If taper is done along entire length, the tailstock offset (in mm)

$$\text{Soln:- } x = L_w \sin \frac{\alpha}{2} \Rightarrow L_w \tan \frac{\alpha}{2}$$

$$x = L_t \tan \frac{\alpha}{2}$$

$$\text{but } \tan \frac{\alpha}{2} = \frac{x}{L_t} = \frac{D_{max} - D_{min}}{2L_t}$$

$$x = L_t \times \frac{D_{max} - D_{min}}{2 \times L_t} = \frac{50 - 38}{2}$$

$$x = 6$$

$$\frac{\sin \theta}{\cos \theta} = \tan \theta$$

If θ is very small $\cos \theta = 1$

$$\sin \theta = \tan \theta$$

$$\sin \frac{\alpha}{2} = \tan \frac{\alpha}{2}$$

$$\left[\sin \frac{\alpha}{2} = \frac{x}{L_w} \right]$$

$$\text{and } \tan \frac{\alpha}{2} = \frac{x}{L_t}$$

$$\frac{x}{L_t} = \frac{x}{L_w}$$

$$L_w = L_t$$

Mradul Rawat

Threading :- It is Continuous Form of helical ridges Formed over Cylinder or Frustum of Cone.

Formed over Cylinder \rightarrow Straight or parallel thread

Formed over Cone \rightarrow Tapered thread.

High quality thread \rightarrow Thread chasing process

The lathe Used For thread chasing is Swiss Automate

Thread are Formed by

- (a) Single point threading tool
- (b) Form tool application.

- Application of thread
- (a) Fastening of two objects.
 - (b) Motion transmission.

* Single point thread tool should ideally have Zero rake angle but practically (-)ive rake angle is Used.

* Thread cutting is a slowest Speed operation in lathe.

\rightarrow Machining Calculation

$$t_m = \frac{L_e \times n}{fN}$$

f = depend upon pitch
pitch is the distance between two adjacent peak and valley

n = no of cuts

- ① Single start thread
1 rev = 1 thread
F = 1P


- ② Double start thread
1 rev = 2 thread
F = 2P

- ③ Triple start thread
1 rev = 3 thread
F = 3P

Note:- If pitch is Not given and No of thread = 8/cm

Gate:- To produce double start thread of pitch 2mm the

$$P = \frac{1}{8} \text{ cm}$$



feed (mm/rev) is $F = 2P = 2 \times 2 = 4 \text{ mm/rev}$

Gate:- Find the time for threading on 3cm Spindle of M.S for length of 15cm. The Number of thread are cut by 3/cm. The lathe run at 88 rpm. Assume approach and overtravel are 0.5cm each and No of Cut for M.S are 7

Solu:- $t_m = \frac{L_e \times n}{fN}$ $L_e = 15 + 0.5 + 0.5$ \Rightarrow No of thread = 3/cm
 $= 16$ $n = 7$ $N = 88 \text{ rpm}$
pitch = 1/3


$$t_m = \frac{16 \times 7}{\frac{1}{3} \times 88} = 3.81 \text{ min}$$

Normal

Tool Setting Errors

(a) Ideal Condition


$$\theta = 0^\circ \quad x = 0 \text{ (offset)}$$



$$(a) \alpha_{eff} = \alpha_{actual}$$

$$(b) C_{eff} = C_{actual}$$

(2) Tool offset above



$$(a) \alpha_{eff} = \alpha_{actual} + \theta$$

$$(b) C_{eff} = C_{act} - \theta$$

Rake $\angle \uparrow$, Clearance $\angle \downarrow$

$$\theta = \sin^{-1} \left(\frac{x}{R} \right)$$


x = offset distance

θ = offset angle

(3) Tool offset Below

α_{eff} & α_{act} are rake angle

C = clearance angle



$$(a) \alpha_{eff} = \alpha_{act} - \theta$$

$$(b) C_{eff} = C_{act} + \theta$$

Rake $\angle \downarrow$, Clearance $\angle \uparrow$

$$\theta = \sin^{-1} \left(\frac{x}{R} \right)$$

$$\alpha_{eff} + C_{eff} = \alpha_{act} + C_{actual}$$

Boxing

Rake angle ↓
Clearance angle ↑

Ques:- while turning a diameter of 90 mm, the turning tool is set below centre line by 5mm, if actual rake angle is 10° and actual clearance angle is 5°, find the effective rake and clearance angle.

Solu:- Tool offset Below

(4)

$x = 5\text{mm}$ $\alpha_{act} = 10^\circ$ $C_{act} = 5^\circ$ $\text{dia} = 90\text{mm}$ $\alpha_{eff} = ?$ $C_{eff} = ?$

$\theta = \sin^{-1}\left(\frac{x}{R}\right) = \sin^{-1}\left(\frac{5}{45}\right) = 6.38^\circ$

$\alpha_{eff} = \alpha_{act} - \theta$
 $\alpha_{eff} = 10 - 6.38 = 3.62^\circ$

$C_{act} + C_{eff} = C_{act} + \theta$
 $= 5 + 6.38 = 11.38^\circ$

* Speed Selection

* The different Speed on a lathe are provided in geometric progression.

$N_{max} = N_{min} \cdot \eta^{n-1}$

Note:- If Machinability indices for work material are 50 means Cutting speed = 50

n = No of Speed available in gear box

N_{max} = Max^m Speed in gear box

N_{min} = Min^m Speed in gear box

Speed range Ratio

$\frac{N_{max}}{N_{min}} = \eta^{n-1} = \frac{V_{max}}{V_{min}} \times \frac{D_{max}}{D_{min}}$

η = Common ratio.

Metal Removal Rate (mm³/min)


$MRR = \frac{\text{Volume}}{\text{Time}}$

Volume = $\frac{\pi}{4} (D_i^2 - D_f^2) \times L$

$t_m = \frac{L}{fN}$

$= \frac{\frac{\pi}{4} (D_i^2 - D_f^2) \times L}{L/fN}$


$M.R.R = \frac{\pi}{4} (D_i^2 - D_f^2) \times fN$ $\frac{\text{mm}^3}{\text{min}}$



$M.R.R = \pi \left[\frac{D_i + D_f}{2} \right] \left[\frac{D_i - D_f}{2} \right] fN$

$= \pi D_{avg} d_T fN \rightarrow V_{avg}$

$M.R.R = f d V_{avg}$



In term of Cutting Velocity [2-D Analysis]


$M.R.R = f d (V \times 1000) \frac{\text{mm}^3}{\text{min}}$
 $\frac{\text{mm}}{\text{rev}} \times \text{mm} \times \frac{\text{m}}{\text{min}} = \frac{\text{mm}^3}{\text{min}}$

Grinding → Highest Cutting Speed.


- (1) Cut gears (2) internal & external Machining (3) enlarge circular & Non circular holes (4) cut keyways etc

Broaching:- Least Cutting Speed

orthogonal cutting tool



- Will Not Remove any material
- Reduce Surface Irregularities
- Removes Very less material and involves partial finishing
- Remove maximum material



* Broaching is highly accurate and high Accuracy of surface finish.

Mradul Rawat

→ No material Removal [because they remove surface roughness or surface irregularity and surface irregularity are in micron level which neglected.]

→ Spline hole are made by Broaching


→ Single point cutting tool may be Orthogonal and may be oblique

oblique cutting → twist drill, helical milling cutter

Orthogonal cutting → Broaching, shaping, planing, slotting

(5)

$$t_m = \frac{Le}{V} = \frac{t + L_r + L_s + L_f}{V} = \frac{t + L_B}{V}$$



$$d = n \times h \Rightarrow n = \frac{d}{h}$$

Total depth of cut = $d_r + d_s$

$$n_r > n_s > n_f$$

$$L = n \times p$$

$$L = \frac{d}{h} \times p$$

$$d_r = n$$

L_B = cutting length of broaching

t = thickness of workpiece

$$L_B = L_r + L_s + L_f$$

(a) Rough teeth

$$L_r = n_r \times p_r$$

$$L_r = \frac{d_r}{h_r} \times p_r$$

$$L_s = n_s \times p_s$$

$$L_s = \frac{d_s}{h_s} \times p_s$$

$$L_f = n_f \times p_f$$

$$d_f = n_f \times h_f$$


n = no of teeth.

Shaping [Size of shaper is given by stroke length]


→ material is removed from surface by using single point reciprocating tool

→ Cutting motion provided to tool whereas lateral feed motion provided workpiece. Material is removed in forward stroke and known as cutting stroke

→ During return stroke no material is removed and hence it is known as idle stroke




* Feed is provided to workpiece during idle stroke of tool and feed is lateral (side by side) [along breadth] and cutting is longitudinal



1 Forward + 1 Return stroke = 1 Complete stroke or one double stroke

No material Removal [idle stroke]

Example:-



Time of shaping = No of stroke \times $\frac{\text{min}}{\text{Stroke}}$

$$t_m = \frac{B}{f} \times \frac{1}{N}$$

$$t_m = \frac{B}{fN}$$

B = width of workpiece

fN = feed velocity ($\frac{\text{mm}}{\text{min}}$)

$$\frac{\text{mm}}{\text{stroke}} \times \frac{\text{Stroke}}{\text{min}} = \frac{\text{mm}}{\text{min}}$$

Mradul Rawat

$$\begin{aligned} \text{Time per stroke (min/stroke)} &= t_f + t_r \\ &= \frac{L_e}{V_f} + \frac{L_e}{V_r} \\ &= \frac{L_e}{V_f} + \frac{1L_e}{V_f} \end{aligned}$$

Note:- $V_f < V_r$
 V_f = Forward Velocity
 V_r = Return Velocity
 $\lambda = \frac{V_f}{V_r} < 1$
 but $V_f = V$

(6)

$$\frac{P}{\text{min Stroke}} = \frac{L_e(1+\lambda)}{V \cdot 1000}$$

$$\text{Stroke/min (N) or rpm of Crank} = \frac{V \times 1000}{L_e(1+\lambda)} \quad \lambda < 1$$

$$\lambda = \text{Ratio of Forward to return Speed} = \frac{V_f}{V_r}$$

$$\lambda = \text{Ratio of Return to Forward time} = \frac{t_r}{t_f} \quad \lambda < 1$$

Note:- In Whitworth GRMM (used in shapers) the velocity of ram is max at Middle of Return stroke.



(2) Reciprocating motion of tool \rightarrow Quick Return Mechanism
 feed motion provided by workpiece \rightarrow Paul and Ratchet Mechanism

Metal Removal Rate in shaping \Rightarrow

$$M.R.R = f_d N L \Rightarrow \frac{\text{mm}}{\text{Stroke}} \times \text{mm} \times \frac{\text{Stroke}}{\text{min}} \times \text{mm} = \frac{\text{mm}^3}{\text{min}}$$

Note:- If Question given Specific energy = 1.4 J/mm^3 and Asked Power

$$\text{Power} = \text{Specific energy} \times M.R.R$$





* It produce more accurate surfaces

* planer is heavier, large and more rigid than shaper so they can withstand heavy vibration.

* More No of cutting tool used simultaneously

Gate:- The similarity b/w shaper and planer is that both are used to produce flat surface

Comparison between Mechanical and hydraulic shaper



(1) Heavier and More rigid as it is a heavy system. As system is heavy due to heavy oil tank [Supress large Vib]

(2) Speed remain constant throughout the stroke

(3) At a given cutting speed, more No of stroke covered

(3) less No of stroke covered at a given cutting speed

Note:- Vertical shaper are called slotter and it has Rotary worktable.


Mradul Rawat

Milling

- Milling is a machining operation in which material is removed by multipoint cutter
- The cutter are mounted on shaft are known as Arbor

(7)

Face milling [Vertical milling]



$$x_{sym} = \frac{1}{2} [D - \sqrt{D^2 - W^2}]$$

Diameter is greater than width of workpiece.

$$x_{asym} = \frac{1}{2} [D - \sqrt{D^2 - (W + 2y)^2}]$$

$$t_m = \frac{L_e}{f_m} = \frac{L_e}{f_t N Z} = \frac{L_e}{f_m} = \frac{L_e}{f_t N Z}$$

$\frac{mm}{min}$ $\frac{mm}{tooth}$ $\frac{rev}{min}$ $\frac{tooth}{rev}$

$$f_m = f_t N Z \quad \text{or} \quad f_t = \frac{f_m}{N Z}$$

f_t = feed per tooth Z = No of teeth
 N = R.P.M

Slot milling [End mill cutter] :- Diameter of cutter = Width of slot


when $D = W$ then $x = \frac{D}{2}$

Note :- कौनसे भी Question हो Milling का पहले x निकालेंगे

Peripheral mill cutter → Horizontal milling (slab milling) → Upmilling or Conventional milling, Down milling or climb milling.


(a) Upmilling or Conventional milling

- * Direction of cutter and W/P will opposite to each other.
- * Tool wear ↑, Tool life ↓
- Surface finish ↓
- * cutter tends to lift the w/p so strong clamping is required
- * chip thickness varies minimum to maximum.



(b) Down milling or Climb milling

- The direction of cutter and W/P will be same
- Tool life ↑, Tool wear ↓
- Surface finish ↑
- cutter tends to push the workpiece toward table, strong clamping is not required
- chip thickness varies maximum to minimum.
- In industry, generally down milling used
- Specific power consumption is low.




Mradul Raw

Compulsory Approach for peripheral milling Cutter

(8)

$$x = \sqrt{d(D-d)}$$



Max^m chip thickness

$$t_{max} = \frac{2f_m}{NZ} \sqrt{\frac{d}{D}}$$

f_m = table feed (mm/min)

Min^m chip thickness = 0

Average chip thickness = $t_{avg} = \frac{t_{max} + t_{min}}{2}$ if $t_{min} = 0$

$$t_{avg} = \frac{t_{max}}{2}$$

Mradul Rawat

Indexing :- (a) Direct Indexing

Bevel Gear is Used
Gear Ratio = 24:1

24 Rev of Index Crank = 1 rev of W/P = 'N' division on workpiece
1 division = $\frac{24}{N}$ rev of Index Crank

For 1 Div

$$ICR/Div = \frac{24}{N}$$

if $N=10$ $ICR = \frac{24}{10} = 2 \frac{4 \times 2}{10 \times 2} = 2 \frac{8}{20}$

For one division, Index Crank Rotates
For one division on workpiece, Index Crank Complete two full Revolution
Followed by 8 hole movement in 20 hole circular plate.

(b) Simple Indexing / Plane Indexing :- Worm gear is Used
Gear Ratio = 40:1

40 rev of Index Crank = 1 Rev of W/P = N Div on W/P

For 1 Div

$$I.C.R = \frac{40}{N}$$

Gate:- For 1 div on W/P, index Crank Complete 1 full rev followed by
10 holes in 30 holes Circle. Find the degree of rev for the workpiece.

Solu:- $ICR = 1 \frac{10}{30} = \frac{40}{30} = \frac{40}{N}$ N=30

N Div on W/P = 1 Rev of W/P

1 Div on W/P = $\frac{1}{N}$ Rev of W/P = $\frac{1}{30} \times 360 = 12^\circ$

Gate:- Using DI Mechanism, if a workpiece is to be divided into 8
equal division then For 1 Div, the degree of rev for Crank and W/P is

Solu:- N division on W/P = 24 rev of index Crank
1 div = $\frac{24}{8} = 3$ rev of Index Crank = $3 \times 360 = 1080^\circ$

\Rightarrow N division on W/P = 1 rev of W/P

1 div = $\frac{1}{8}$ rev of workpiece = $\frac{1}{8} \times 360 = 45^\circ$ rev of W/P

Type of Cutter (a) End Mill (b) peripheral mill (c) Side mill (d) Form mill (e) Straddle mill → No of milling Cutters mounted on arbor is 2
 (f) Gang milling :- Two or more Cutters are Combined to remove material Simultaneously From a large W/P. → They produce flat Vertical surface on both Side of W/P.

Grinding :- Grinding wheel # Tool, Abrasive (ताँबा)
 * Grinding wheel is balanced frequently to reduce Cutting time.
 * It operates at highest Cutting Speed to reduce Cutting time.
 * It consumes highest Specific power Consumption or highest Specific Cutting energy because wheel has multiple cutting edge with more of (-)ive rake angle then more force required at some point.

Specific Power Consumption [J/mm³] ⇒ $C = \frac{\text{Power}}{M \cdot R \cdot R} = \frac{F_c V}{M \cdot R \cdot R} = \frac{F_c V}{b d V}$
 b = width (mm), d = depth of cut (mm)
 V = Table feed (mm/min) F_c = Cutting Force (N), V = Cutting Speed = πDN $\frac{m}{min}$.

If MRR ↓ then C ↑ (or), V ↑, C ↑
 * Abrasive are Not Used in Burnishing process.


Reason For low M.R.R (a) Size effect (b) Welding effect (c) large (-)ive rake angle.
 Turning Grinding (Power)_T = (Power)_G ⇒ C = (Power) / MRR → same
 C_T < C_G (M.R.R)_G is low due to Size effect
 Turning Grinding (M.R.R)_T = (M.R.R)_G C_T < C_G ↑ C = $\frac{F_c V}{(M.R.R)}$ Same
 Due to high Cutting Velocity

Mechanism of Grinding :- when Abrasive remove material then it is subjected to wear. The worn out abrasive are pulled off the wheel by the rubbing force b/w the wheel and the work when the outer layer are pulled out, the inner fresh layer get a chance for material removal, This is known as Self sharpening behaviour of Grinding wheel.

$G \cdot R = \frac{V_m}{V_w} = \frac{\text{Volume of material removal}}{\text{Volume of wheel wear}} = \frac{l \times b \times d}{\frac{\pi}{4} \times w \times [d_i^2 - d_f^2]}$

$V_m = l \times b \times d$
 $V_w = V_i - V_f = \frac{\pi}{4} D_i^2 \omega - \frac{\pi}{4} D_f^2 \omega = \frac{\pi}{4} \times w [d_i^2 - d_f^2]$
 wheel undergoes radial wear
 D_i = 200 mm D_f = D_i - 2r
 r = 40 μm = 200 - 0.8 = 199.2

Grinding wheel Specifications



Ques:- why diamond is not used for grinding steel?
 Solu:- Due to diffusion of Carbon atoms in steel, machinability of steel decreases.

In term of Hardness [Diamond > CBN > SiC > Al₂O₃]

* Silicon Carbide is Natural Abrasive material while Al₂O₃, CBN are Synthetic material

| | |
|--------------------------------|--------------------------------|
| Abrasive material | Trade Name |
| Silicon Carbide [SiC] | → Carborundum & Crystolon |
| Al ₂ O ₃ | → Aloxite, Alundum and Borolon |
| CBN | → Borazon |

(10)

② Grain Size or Grit Size

| | |
|-------------------------------------|------------------------------------|
| G.S.N | G.S |
| (Grain Size No) | |
| 10-24 | Coarse |
| 30-60 | Medium |
| 80-180 | fine |
| 220-600 | Very fine |
| Grain Size = $\frac{1}{G.S.N}$ inch | = $\frac{1}{G.S.N} \times 25.4$ mm |

* when material is removal in Bulk, Coarse grain is used and this is called Roughing operation

* In case of Finishing & Super finishing operation Fine grain structure is used at high speed.

1 inch = 25.4 mm

Example A(27) K 12 V

Abrasive (Al₂O₃) ⇒ Grain Size = $\frac{1}{27} \times 25.4$ mm = 0.9 mm

* Hardness or Grade :- The ability of bond to retain its Abrasives

- A - H → Soft wheel - Hard W/P.
- I - P → Medium wheel - Medium Workpiece.
- Q - Z → Hard wheel - Soft Workpiece.

Case:- 1 Hard W/P and Hard wheel :- If the W/P is hard, rubbing force will be high and abrasive will wear out quickly but since the wheel is also hard it won't allow the abrasive to be pulled off. Thus worn out abrasive will rub on the workpiece and no material will be removed, more over fresh layer of abrasive will not get a chance of machining. This is known as Glazing or Blunt wheel grinding. After glazing is observed a single point turning tool can be used to remove the worn out abrasive forcefully from the grinding wheel. This process is known as Dressing.

Tool life of grinding wheel is defined as The time period b/w two successive wheel dressing.

Structure < OPEN DENSE It refers to the Average gap b/w two consecutive abrasive.

Structure Number ∝ Average gap.

SN-[0-7] Dense [Finish grinding] SN [8-16] Open [Rough grinding]

Dense structure ⇒ For Finish grinding & Hard W/P

Open structure ⇒ For rough grinding & Soft workpiece.

Average gap b/w Abrasive = $\frac{\text{Structure No}}{1000}$ inches.

* If Rough grinding is performed using dense structure chips will not find enough space to flow out and chips will be clogged within the interspaces of abrasive. This is known as loading of grinding wheel.

Other Reason of loading

- * If the W/P is too soft
- * If r.p.m of grinding wheel is low
- * If Cutting fluid is not properly supplied

Soft material cannot be economically grinded due to production of long continuous chips in case of soft material, continuous chips forced to enter into the spaces between the abrasive grain and leads to frequent

clogging of wheel.

Mradul Rawat

BOND:- V-BOND - Vitified Bond → Latin word "Vitreum" [glass like]

[clay + feldspar] $\xrightarrow{\Delta 1250^{\circ}\text{C}}$ Hard glass like bond. → Vitified Bond (11)
 Binder $\xrightarrow{\Delta 1250^{\circ}\text{C}}$ This process is known as Vitification. $v \sim 2500$

* V Bond is Not Used For high Speed grinding because it has hard & brittle and under the influence of high Centrifugal Force, the bond may break. It has highly reliable for slow and medium Speed grinding.

* high thermally stable and chemically inert toward cutting fluid.

(b) Rubber Bond :- Used for soft wheel [Used for polishing & centreless grinding]
 (c) Sodium Silicate :- NaSiO_3 It Used as a bonding material for grinding wheel.
 * It is known as Water glass

* It is Used for medium & high Speed grinding wheel.

"Creep" feed Grinding (Single pass Grinding)

In this process, the table feed will be extremely slow and the depth of cut will be high such the grinding involves one pass only

Truing :- It is a process of bringing the grinding wheel from an outshaped form into proper roundness and circularity by the help of single point turning tool.

Centreless Grinding :-

* Direction of workpiece is opposite to all other wheels [Guiding or Regulating wheel or grinding wheel]

* There will be No Fixed Centre provided to W/P

* It is generally Used for Solid or hollow cylindrical Specimen

* In Centreless grinding, the W/P Centre above the line joining the two wheel centre.

$$F = \pi D N \sin \alpha$$

D = Regulating wheel dia
 N = Speed of Regulating wheel.

* Solid Cylinder \Rightarrow External C.G $\Rightarrow R \cdot W < G \cdot W$





* hollow Cylinder \Rightarrow internal C.G $\Rightarrow R \cdot W > G \cdot W$

Drilling :- It is Machining process in which holes are produced such that both cutting motion and feed motion can be provided to the tool.

For large diameter holes :- BTA [Boring tool & trepanning] & Gun drill

Punching \rightarrow Impact shear

Drilling \rightarrow Gradual shear.



Hole
 Blind ($L < t$)
 Through ($L > t$)

If α = Not given

$$t_m = \frac{L_e}{fN}$$

mm/rev rev/min

* If point \angle is given then we $\tan \frac{\alpha}{2} = \frac{D/2}{x}$

always find Compulsory Approach \rightarrow

$$x = \frac{D/2}{\tan(\frac{\alpha}{2})}$$

$$\text{Blind hole} = x = 0.3D$$

$$\text{Through hole} = x = 0.5D$$

$$L_e = t + l_a + l_o + x$$

Mradul Rawat

Note:- Double fluted Drill का मतलब है जो f_t की value है उससे ϕ का Multiply कर दी

For exp:- $F_t = \text{Feed per tooth} = 0.2 \text{ mm}$
 feed per flute mean 1 rev = 2 flutes

feed per rev = $0.4 \frac{\text{mm}}{\text{rev}}$

(a) No of holes produced = $\frac{T}{T_m}$ | No of tool change = $\frac{t_{nc}}{T}$
 or
 No of part produced

$T_m = \text{Machining Time}$
 $T = \text{tool life}$

(c) Production time per hole
 $= \frac{\text{Total time}}{\text{Total hole}}$ (12)

Note:- If in Question, given that
 (1) Neglect Approach and overtravel
 $L_e = t$

Approach and overtravel is equal to
 radius of drill
 $L_e = t + 0.5D$


Other Machining Operations

- * Boring :- Hole enlargement process
- * Counter Boring :- enlargement upto certain depth to accommodate bolt heads
- * Counter Sinking :- making a conical enlargement at one end of hole.
 OR It is a machining process that make a cone shaped recess at the top of hole to accommodate screw head.

Major dia of hole \leq Major dia of tool

* Spot facing :- In this process internal chips will be removed from the enlarged portion of hole. For proper seating of bolt heads. In this process end mill cutter will be used in drilling machine.

Drilling > Boring > Counter boring > Spot Facing.



* Trepanning :- A trepanning tool used in lathe, in this process a large dia holes are produced without drilling and first used in Post-Mortem operation

- * trepanning is done for through hole only
- * In trepanning the entire material is not converted into chips

Large dia hole = Trepanning + Boring

* Honning :- Best surface finish or commonly performed for internal surfaces
 It is a super finishing operation and order of surface roughness = $0.01 \mu\text{m}$
 $= 0.01 \text{ micron}$

- Used for finishing cylinder in I.C engine
- Not used in material removal (only for finishing)

* Lapping :- It is an external finishing operation.

* Core drilling :- Holes is produced by casting using Cores.

* Tapping :- Internal thread making process.

* Open die threading :- External thread only.

(a) Give Best Accuracy
 (b) Sizing and Finishing a hole
 Reamer & Finishing a

REAMING (c) Improved dimensional tolerance
 (d) It require a pre-exist hole.

does not produce hole it can enlarge hole

Right hand helix [$\psi > 0$]
 * pull chips toward back of reamer or shank
 * Sizing a blind hole
 * Used for hard & strong W/P.

Left hand helix
 * push the chip toward the tip of reamer
 * Machining through hole
 * Use for soft and ductile workpiece

Straight fluted [$\psi = 0$]
 * Rake angle is zero
 * fluted are || to axis
 * No chip lifting capacity
 * chip will fall under the action of gravity
 * Used for through holes machining


Miradul Rawat

* Reamers are having even Number of flutes to reduce the Cutting Forces. (13)


Note:- Hard W/P, through hole machining which reamer will be Used as helix angle $\uparrow \rightarrow$ Strength \downarrow \because If helix angle = 0, strength is more. So straight fluted reamer will be Used.

* Inverted drilling Machine :- In this process, high feed and heavy depth of cut is provided, Generally Used for deep hole drilling and it is also known as oil hole drill.

* Radial drilling Machine
 $V = N \times 1P \rightarrow$ Single start
 $V = N \times 2P \rightarrow$ Double start
 $V \Rightarrow \frac{\text{rev}}{\text{min}} \times \frac{\text{mm}}{\text{rev}} = \frac{\text{mm}}{\text{min}}$
 $N = \text{s.p.m of Lead Screw}$
 $P = \text{pitch of lead Screw}$
 $V = \text{Vertical Speed of radial Arm.}$



Twist Drill Geometry



Note:- why we provide helix (or) Flute.

- \rightarrow chips lifting Capacity
- \rightarrow To provide Variable rake angle
- * To break the chips
- * To enable the Cutting fluid to reach the Cutting edge.

Note:- The Cutting portion of drill is to be welded to its shank, The best suited process is Friction welding.

- \rightarrow Rake \angle is less \rightarrow strength is more
- Rake \angle is more \rightarrow Ease in chip flow

* Rake angle is minimum at dead center and to impart more strength to drill and Rake angle is maximum at outermost periphery to keep the chip flow better and becomes equal to helix angle.

$\text{Maxm rake angle} = \text{Helix Angle}$
 $\text{Rake angle} \leq \text{Helix Angle}$

$\text{Helix Angle} \propto \text{Rake Angle} \propto \frac{1}{\text{Point Angle}}$

Soft and ductile W/P \Rightarrow Point Angle \downarrow
 Rake Angle \uparrow
 helix Angle \uparrow [blw $34^\circ - 38^\circ$] known as fast helix drill [high helix rate
 chip lifting Capacity high, low drill strength]

Hard & strong W/P \Rightarrow Point Angle \uparrow
 Rake Angle \downarrow
 helix Angle \downarrow [blw $12^\circ - 22^\circ$] know as slow helix drill
 \Rightarrow less helix rate, chip lifting Capacity will be poor due to slow helix rate, Drill strength is high and Used For deep holes

Regular helix drill $\Rightarrow \psi = 24^\circ - 32^\circ$
 It is Used for medium W/P \rightarrow Brass, Bronze

Mradul

Point Angles - HCS $\rightarrow 120^\circ$
Carbides $\rightarrow 135-150^\circ$
Mild steel $\rightarrow 118^\circ$

Cast Iron = 116° [Anomalous behaviour]
In tool = $60^\circ - 80^\circ$

(14)

* Shank is of two types :-

(1) Straight [3-Jaw chuck]
 $D < 12.5 \text{ mm}$
For small hole diameter

(2) Tapered (Self locking tendency)
 $D > 12.5$
General purpose

Chip lifting $\rightarrow S < R < F$
Drill strength $\rightarrow F < R < S$
R = regular
S = slow
F = fast

* Deep hole drilling

(1) Gun drilling $\rightarrow 3 \text{ mm} \leq \text{Drill} \leq 50 \text{ mm}$
(2) BTA $\rightarrow 15 \text{ mm} \leq \text{Drill} \leq 600 \text{ mm}$

BTA \Rightarrow Boring and Trepanning

Note:- Thrust Force \downarrow [Point Angle \downarrow , helix angle \uparrow]

* Centre lathe :- knurling

- Lathe :- Lead Screw (or) Apron Mechanism
- Shaper :- Rocker Arm (or) Quick Return Mechanism
- Engraver :- Pantograph Mech. Press :- Toggle Mechanism
- Automobile :- Ackermann Mech.
- Drilling M/c :- flute (or) Counter Boring
- Milling M/c :- Universal indexing (or) Indexing Mech. or slotting
- Centreless Grinding :- Regulating Mech.
- Grinding :- Dressing.

😊 Mradul Rawat 😊

Mradul Rawat